

Report ID: 19,802,761 Version: 1 09 Sep 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2010		FJU69	Reg Expiry:	25 Nov 2019	Engine			
	28 May 2020	Odometer:	125,494 Kms	Good No:	19802761	Oil level	~		
VIN:	MNTCPGD22A000012		123,194 1113	Service Histor		Smoke & fumes	~		
					,. 110	Performance	~		-
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		1
		_				Performance	~		
Key:	SC	-0	P SC SC		SC	Radiator / Hoses (visual)	<i>v</i> <i>v</i>		
S = scratch	Se	20		10c	X	Transmission	V		
D = dent	s sc all			The	EID ID				1
R = rust				10		Operation Noise	~		
PT = paint def	ect 📊			+	SC SC		~		
C = crack P = pin dent	Ht			-		Clutch	~		
* = decals	sc dr				Ell'As	CV joints			~
SC = stone chips						Wheel bearings	~		
W = significant scuffs W SC SC D						Brakes		1	<del></del>
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		<u> </u>
Rust in body seams on tailgate. Stonechips on windscreen.						Tyres (lowest observed tread depth of tyres)			
RF window has issues. Wear on steering wheel.						Left front		4	mm
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		mm
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Outer edge	wear LF tyre. Shocks ha	ave wear.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
	_					Window winder FR		~	
General Comments					Window winder RL	~			
Drives ok.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
								•	
Inspected by: Roger King Date: 09 Sep 2019									

Name: .....

Signature: .....