

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System

	Noise Noise	sual)		
Key: S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent	B W S S B S D W S Radiator / Hoses (vis Transmission Operation Noise	-		
Key: $S = scratch$ $D = dent$ $R = rust$ $PT = paint defect$ $C = crack$ $P = pin dent$	Radiator / Hoses (vis Transmission Operation Noise	iual) 🖌		
D = dent R = rust PT = paint defect C = crack P = pin dent	S Operation Noise	<u> </u>		
R = rust SC W PT = paint defect C = crack P = pin dent	Noise Noise			
C = crack P = pin dent		~		
P = pin dent		~		
5.50	Clutch			
* = decals	CV joints	~		
	Wheel bearings	~		
SC = stone chips W = significant scuffs	Brakes			-
S S S	W SD SD W SP Performance	~		
Body Inspection (Note: some defects & blemishes may not be displayed in the diagram Hand Brake	~		
Chip windscreen insid		d tread deptl	h of tyre	es)
Front tyres inner edge			3	m
	Right front		3	m
	Left rear		2	m
Conditions During	g Body Inspection: Dry Right rear		4	m
	Spare		Yes	
Under Carriage &	Under Bonnet Inspection Comments Suspension	I		
	Suspension perform	nance 🖌		
	Steering performance	ce 🖌		
	Shock absorbers	~		
	Air Conditioning / He	eater		-
	Operation	~		
Interior Comment		es		
Seats	Average Head lights	~		
	Average Tail lights	~		
		~		
Carpets	Indicators			+
Carpets Panels	Average Indicators Dashboard warning	lights 🖌		
Panels	Average Dashboard warning Winers (front & rear)	-		
	Average Dashboard warning	-		
Panels	Average Dashboard warning Average Wipers (front & rear)			
Panels	Average Dashboard warning Average Wipers (front & rear) Window winder FL Window winder FR			
Panels Dashboard	Average Dashboard warning Average Wipers (front & rear) Window winder FL Window winder FR			
Panels Dashboard	Average Dashboard warning Average Dashboard warning Wipers (front & rear) Window winder FL Window winder FR Window winder RL			
Panels Dashboard	Average Dashboard warning Average Wipers (front & rear) Average Window winder FL Window winder FR Window winder RL Window winder RR Window winder RR			
Panels Dashboard	Average Dashboard warning Average Wipers (front & rear) Average Window winder FL Window winder FR Window winder RR Rear view mirrors Rear view mirrors			
Panels Dashboard	Average Dashboard warning Average Wipers (front & rear) Average Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only Radio (basic test only)	y) v v v v v v v v v v v v v		
Interior Comment	Average Head lights Average Tail lights	v v		-

Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No

Inspected by: John Lindsay

11 Sep 2019 Date:

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Report ID: 19,803,637 Version: 1 Created: 11 Sep 2019

Pass

V

V

V

V

Noise

Fail

N/A

~

mm mm mm mm

I have read and understood this condition guide.

Name:

Kms:

Signature:

V

V

~