

Report ID: 19,803,905 Version: 2 27 Sep 2019 Created:

Make:	Mitsubishi	Model:	Colt	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	<b>Registration:</b>	CUF616	<b>Reg Expiry:</b>	20 Mar 2020	Engine			
WoF Expiry:	02 Oct 2020	Odometer:	108,975 Kms	Good No:	19803905	Oil level	~		
VIN:	JMAXSZ23A5Z000180	Next Service:	118971	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	Р		SC			Performance	~		
Key:	L LL	-0				Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
R = rust	SC W			210		Operation	~		
PT = paint defe	ect NP				101h	Noise	~		
C = crack						Clutch			~
P = pin dent	HIR				2414	CV joints	~		
* = decals	sc 916			Tool .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant			SC			Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						<b>Tyres</b> (lowest observed tread depth of tyres)			ès)
						Left front	1.	.5	mm
						Right front	1.	.5	mm
						Left rear	2	.0	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mn		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
·						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Chris Vanner Date: 13 Sep 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....