

## Report ID: 19,804,069 Version: 1 Created: 23 Sep 2019

Make:	Nissan	Model:	Pulsar	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2003	<b>Registration:</b>	BHT455	Reg Expiry:	23 Jan 2020	Engine			
WoF Expiry:	24 Nov 2019	Odometer:	171,179 Kms	Good No:	19804069	Oil level	~		
VIN:	SJNFBAN16A0400646	Next Service:	173000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
Note: This report is not a warranty						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged ic	or an additional (	.narge.	Coolant condition	~		
			S D			Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				210	E SW	Operation	~		
PT = paint def	ect NP	Ir I			11111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dle				74116	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scuris SC W PT S S						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Front tyres borderline						Tyres (lowest observed tread	d depth	of tyre	es)
Right rear tyre nail slow leak, inner side wall starting to crack						Left front	Left front 1.5		
						Right front	1	.5	mm
						Left rear	2	.5	mm
Conditions During Body Inspection: Dry						Right rear 3.0 mi			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	centre con	sole lid broken				Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys 2			
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanisms Timing Chain						Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Greg Morgan Date: 11 Sep 2019									
Inspected by: Greg Morgan Date: 11 Sep 2019									

Name: .....

Signature: .....