

Report ID: 19,808,328


Version: 1

Created: 18 Sep 2019

Make:	Honda	Model:	CRV	Body Style:	SUV
Year:	2004	Registration:	CHS779	Reg Expiry:	22 Sep 2019
WoF Expiry:	25 Mar 2020	Odometer:	105,026 Kms	Good No:	19808328
VIN:	JHLRD78805C200869	Next Service: Service History: No		<b>y:</b> No	

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Conditions	During	Body	Inspection:	Drv

## **Under Carriage & Under Bonnet Inspection Comments**

Underbody surface rust Rear brake pads low

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Good		
Dashboard	Good		

## **General Comments**

AWD

Road Conditions During Test Drive: Dry

**Timing Chain** Engine Timing Mechanism:

Evidence of Cam Belt Replacement: Not Applicable Kms:

**Bobby Zhong** Inspected by:

Name: .....

	Pass	Fail	N/A
Engine	•		
Oil level	~		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	~		
Cooling System	•		•
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	1		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	l		
Performance		~	
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	 es)
Left front	· ·		mm
Right front		5	mm
Left rear	2		mm
Right rear	3		mm
Spare	Yes		
Suspension			
Suspension performance	<b>V</b>		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FI	~		
Window winder FR	~		
Window winder RL	<i>v</i>		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
	· ·		
Number of keys	1		
Central locking	<i>'</i>		-
Domoto la alcia a			
Remote locking	<i>\</i>		-
Remote locking Sat. Nav. (basic test only) Reversing camera			V

Signature: .....