

Report ID: 19,809,324 Version: 2 18 Nov 2019 Created:

Make:	Mitsubishi	Model:	Delica	Body Style:	SUV		Pass	Fail	N/A
Year:	2010	Registration:		Reg Expiry:		Engine			L
WoF Expiry:	20 Jun 2020	Odometer:	84,384 Kms	Good No:	19809324	Oil level	~		
VIN:	7AT0CJ0PX19501656	Next Service:	89,292kms	Service Histor	' y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and milaago	Parts have not	t been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	iical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	P P	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	- HIE			TIN		Operation	~		
PT = paint defe	ect NP			$\left(\right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIC				74114	CV joints	~		
* = decals	sc 916			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs		PP			Performance	~		
Dadutur		Note: son	ne defects & blemishes	may not be disr	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyre			
									mm
						Right front	7		mm
						Left rear			mm
						Right rear			 mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
Front whee	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Contr	Good					Head lights	~		[
Seats						Tail lights	~		
Carpets	Good					Indicators	v v		
	Good								
Panels						Dashboard warning lights Wipers (front & rear)	v		
Dashboa	rd Good					Window winder FL	v		
						Window winder FL Window winder FR	v		
General (Comments					Window winder FR	v		
							V		
						Window winder RR	~		
						Rear view mirrors	v		
						Radio (basic test only)	v		
						CD (basic test only)	v		<u> </u>
						Number of keys	2		I
Road Conditions During Test Drive: Dry						Central locking	~		
Enaine Tir	ming Mechanism:	Timing	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Xinghui Lin Date: 18 Nov 2019									

I have read and understood this condition guide.

Name: