

Report ID: 19,809,952 Version: 1 19 Jun 2020 Created:

| Make: | Toyota | Model: | Avensis | Body Style: | Wagon | | Pass | Fail | N/A | |
|--|--------------------------|----------------------|------------------------|--------------------|----------------------|--|----------------------|------|-----|--|
| Year: | 2011 | Registration: | | Reg Expiry: | - | Engine | 1 | 1 | I | |
| WoF Expiry: | 03 Sep 2020 | Odometer: | 96,042 Kms | Good No: | 19809952 | Oil level | ~ | | | |
| VIN: | 7ΑΤ0H63MX1900109€ | Next Service: | 105000 | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | | | - | Performance | ~ | | | |
| | port is not a warranty | | f | Danta harra nat | | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | | | | |
| D = dent | GIE | | | The | | Operation | ~ | | | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | | |
| PT = paint defects C = crack | | | | | | Clutch | • | | ~ | |
| P = pin dent | Ho | | | | | CV joints | ~ | | | |
| * = decals | 1916 | | | AL. | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | | |
| W = significant scuffs | | | | | | Performance | ~ | | | |
| | | Note: con | ne defects & blemishes | may not be disr | laved in the diagram | Hand Brake | <i>v</i> <i>v</i> | | | |
| Body Insp | pection Comments | Note. son | le délects & blemisnes | illay not be disp | hayeu in the diagram | | | | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front | | 1 | mm | |
| | | | | | | Right front | | 1 | mm | |
| | | | | | | Left rear | | 1 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear 4 | | mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | | |
| | inage & onder bor | metmspectic | <u>on comments</u> | | | Suspension | | | | |
| | | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | Operation 🖌 | | | | |
| Interior Comments Good | | | | | | Electrical / Accessories | | | | |
| Seats | Good | | | | | Head lights | ~ | | | |
| Carpets | Good | | | | | Tail lights | ~ | | | |
| | | | | | | Indicators | ~ | | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | | |
| Dashboa | Good | | | | | Wipers (front & rear) | ~ | | | |
| | | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | ~ | | | |
| General Comments | | | | | Window winder RL | ~ | | | | |
| 2WD | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 2 | | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | | |
| | | | | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ | |
| | | | | | | | | | | |
| Inspected by: Bobby Zhong Date: 19 Jun 2020 | | | | | | | | | | |
| | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: