

Basic Vehicle Condition Guide

Report ID: 19,810,053


Version: 2

Created: 24 Sep 2019

Make: Model: Holden Spark **Body Style:** Hatchback Year: 2016 Registration: KBE512 Reg Expiry: 12 Dec 2019 WoF Expiry: **Odometer: Good No:** 24 Sep 2020 37,754 Kms 19810053 VIN: KL3DC48A4HC718557 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

stoneships on windscreen

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comments			
Seats	Good		
Carpets	missing floor mat		
Panels	Average		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	<i>V V</i>			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	V			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	l depth	of tyre	es)	
Left front		3	mm	
Right front	:	3	mm	
Left rear		5	mm	
Right rear		 5	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights				
Indicators	V			
Dashboard warning lights	V			
Wipers (front & rear)	~			
Window winder FL	V			
Window winder FR				
Window winder RL	V			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)			~	
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			
246 2000				

I have read and understood this condition guide.

Bobby Zhong

Name:

Signature:

24 Sep 2019