

Basic Vehicle Condition Guide

Report ID: 19,810,497

Version: 6

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 04 Dec 2019

Fail

Pass

~

~

/

1

1

Tyres (lowest observed tread depth of tyres)

N/A

/

mm

mm

mm

 mm

1

1

5

5

5

1

/

/

/


1

Yes

Make: Model: Toyota Hiace **Body Style:** Van Year: 2009 Registration: LSL699 **Reg Expiry:** 11 Nov 2019 WoF Expiry: **Odometer:** 10 Oct 2020 159,866 Kms **Good No:** 19810497 VIN: 7AT0H60FX18099414 **Next Service:** 167000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left side mirror cover missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive

Interior Comments								
Seats	Good							
Carpets	Good							
Panels	Good							
Dashboard	Good							

General Comments

Inspected by:

Aftermarket refrigerated cargo area AC vent broken

Road Conditions During Test Drive:

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Number of keys 2 1 Central locking Dry Remote locking Sat. Nav. (basic test only) ~ Kms: Reversing camera 04 Dec 2019 Date: Name: Signature:

П	nave	read	and	und	lerstoo	d this	cond	ition	guide.

Jason Law