

Report ID: 19,811,075 Version: 1 18 Sep 2019 Created:

Make: Ho	onda	Model:	Integra	Body Style:	Sports Car		Pass	Fail	N/A
Year: 19			SW993	Reg Expiry:	16 Dec 2019	Engine			L
	Oct 2019	Odometer:	182,737 Kms	Good No:	19811075	Oil level		~	
	MDC23800S100014	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	rt is not a warranty		f	Danta harra nat	haan dhamaadad ay	Noise	~		
diagnostic testin	g undertaken. The v	ehicle has been	for age and mileage. driven up to 50km/h	from cold. The	/endor recommends	Cooling System	•		<u> </u>
a full mechanical	l inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0		-161-	D PT	Radiator / Hoses (visual)	~		
S = scratch	Re	A U			X	Transmission	•		
D = dent	sscw 6/6			10	SC W	Operation	~		
R = rust PT = paint defect	—			í In	JHIH	Noise	~		
C = crack					R	Clutch	· ·		
P = pin dent						CV joints	~		
* = decals	SPTSC 910			- AL	EII PR	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scu	uffs D SC W	-	SD		S D PT	Performance	~		
		Note: som	le defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
· · ·	tion Comments	Note: Joh		indy not be disp	ayea in the diagram		-	oftyro	
Windscreen stone chips in CVA Left and right sides drip rail rust						Tyres (lowest observed tread depth of tyres) Left front 2 mr			mm
Both rear tyres outer edge wear						Right front			
Right side drip	rail chipped					Left rear	2		mm
							2		mm
Conditions During Body Inspection: Dry									mm
Under Carria	age & Under Bon	net Inspectio	on Comments			Spare		Yes	
6 cd charger ca	-	ince inspectio	<u>in comments</u>			Suspension			
One remote wo						Suspension performance	~		<u> </u>
No oil Left outer cv boot leaking/broken						Steering performance	~		<u> </u>
Radiator cross member oxidisation						Shock absorbers	~		
Radio aerial not	t retracting					Air Conditioning / Heater			
Interior Com	nments					Operation	~		
Seats worn and marks						Electrical / Accessories			
Seats						Head lights	~		-
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		
Panels						Dashboard warning lights	~		<u> </u>
Dashboard	Average					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
General Con	nments					Window winder FR	~		<u> </u>
	<u>minerits</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		──
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
L						Number of keys	2		
Road Condit	ions During Test	Drive:	Dry			Central locking			~
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
		ement: N	U	Kms:		Reversing camera			~
Inspected by	y: John Lindsay					Date: 18 Sep 20	19		
	,,								

I have read and understood this condition guide.

Name:

Signature: