



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,812,138
Version:	1
Created:	19 Sep 2019

Make:	Nissan	Body Style:	Hatchback
Model:	Note	VIN:	7AT0DH79X19009048
Year:	2016	Odometer:	86,186 Kms
Road Conditions During Test Drive:	Dry		

Electrical		Cooling System		Exterior	
1	Battery	✓	55	Coolant Condition	✓
2	Headlights	✓	56	Performance	✓
3	Tail Lights	✓	57	Radiator/Hoses (visual)	✓
4	High Stop Light	✓	Suspension		
5	Front Right Indicators	✓	58	Suspension Performance	✓
6	Front Left Indicators	✓	59	Steering Performance	✓
7	Rear Right Indicators	✓	60	Shock Absorbers	✓
8	Rear Left Indicators	✓	Wheels and Tyres		
9	Reversing Lights	✓	61	Left Front	5 mm
10	Rear Reflectors	✓	62	Right Front	5 mm
11	Hazard Lights	✓	63	Left Rear	4 mm
12	Courtesy Lights	✓	64	Right Rear	4 mm
13	Dashboard Lights	✓	65	Spare	No
14	Dashboard Dimmer Switch	•	66	Tools	✓
15	Number Plate Light	✓	Interior		
16	Dashboard Warning Lights	✓	67	AC Operation	✓
17	Speedo	✓	68	Heater Fan	✓
18	Odometer	✓	69	Seatbelts	✓
19	Rev Counter	•	70	Horn	✓
20	Fuel Gauge	✓	71	Seat Heaters	•
21	Wipers Front/Rear	✓	72	Sun Visors	✓
22	Window Opener FL	✓	73	Sun Visors Lights/Mirrors	✓
23	Window Opener FR	✓	74	Seats	Good
24	Window Opener RL	✓	75	Carpets	Good
25	Window Opener RR	✓	76	Panels	Good
26	Rear View Mirrors	✓	77	Dashboard	Good
27	Radio (Basic Test Only)	✓	Turners Certification Key:		✓ = Pass
28	CD (Basic Test Only)	✓			✗ = Fail
29	Boot Open Switch	✓			• = Not applicable for this vehicle
30 Fuel Flap Release		✓			
31 Reversing Camera		✓			
32 USB Port		•			
33 Window Lock Switch		✓			
Transmission and Drive					
34 Operation		✓			
35 Noise		✓			
36 Clutch		•			
37 CV Joints		✓			
38 Wheel Bearing		✓			
39 Wheel Balance		✓			
40 Gearbox (Manual)		•			
41 Engine Timing		Timing Chain			
42 Evidence of Cam Belt Replacement		Not Applicable			
43 Replaced at (odometer reading)					
Brakes					
44 Front Brakes		✓			
45 Rear Brakes		✓			
46 Handbrake		✓			
Keys and Locking					
47 Central Locking		✓			
48 Remote Locking		✓			
49 Number of Keys		2			
Engine					
50 Oil Level		✓			
51 Smokes and Fumes		✓			
52 Performance		✓			
53 Noise		✓			
54 Starter Motor		✓			
78	Under Carriage	Good			
79	Sun Roof Operation	•			
80	Front Windscreen (no chips)	Good			
81	Back Windscreen (no chips)	Good			
82	Side Windows (no chips)	Good			
83	Front Wiper Blades	Good			
84	Rear Wiper Blade	Good			
85	R/H Mirror	Good			
86	L/H Mirror	Good			
87	L/F Guard	Good			
88	R/F Guard	Good			
89	L/H Doors	Good			
90	R/H Doors	Good			
91	L/H Sill	Good			
92	R/H Sill	Good			
93	Boot/Tail Gate	Good			
94	Front Bumper	Good			
95	Rear Bumper	Good			
96	Roof	Good			
97	Bonnet	Good			
98	Fuel Cap	✓			
99	Mud Flaps	✓			
100	WOF	✓			

Inspected by:	John Lindsay	Date:	19 Sep 2019
I have read and understood this condition guide:			
Name:		Signature:	