

Report ID: 19,813,764 Version: 1 23 Sep 2019 Created:

Signature:

Make:	Subaru	Model:	Legacy	Body Style:	Sedan		Pass	Fail	N/A
Year:	1999	Registration:	ZI7903	Reg Expiry:	23 Jul 2020	Engine			L
WoF Expiry:		Odometer:	234,227 Kms	Good No:	19813764	Oil level	~		
VIN:	7A8GF0B0799034708			Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged f	for an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	SC P		s	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO	$\overline{\frown}$		XXX	Transmission	•		I
D = dent	c sc 6/6				EL SC	Operation	~		
R = rust PT = paint def					JHIH	Noise	~		
C = crack				+	D	Clutch			~
P = pin dent						CV joints	~		
* = decals	sc gig					Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs SC W		SRP P	5 Vw		Performance	~		
		Natarcam			layed in the diagram	Hand Brake	<i>v</i> <i>v</i>		
	pection Comments	10000.3011	le délects à blemisme	indy not be disp	layed in the diagram		•	oftwo	(
Rear Panel Rusty.						Tyres (lowest observed tread depth of tyres)			
						Left front	7.		mm
						Right front	7.		mm
						Left rear	5.	-	mm
Conditions During Body Inspection: Wet						Right rear	5.0		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	-	•		cooperation from sta	oring Dack	Suspension			
Sunacerus	t on under body of vehi	cie, oli seepage i	ower engine area, on	seepage nom ste	ening Rack ,	Suspension performance	~		!
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	<u>г т</u>		
Interior Comments						Operation 🖌			
Poor						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		L
	Deer					Indicators	~		
Panels	Poor					Dashboard warning lights	~		L
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
/						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
-	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 18	80,000	Reversing camera			~
							10		
Inspecte	d by: Chris Buckley					Date: 23 Sep 20	19		

I have read and understood this condition guide.

Name: