

Report ID: 19,814,331 Version: 4 14 Jan 2020 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	FHH261	<b>Reg Expiry:</b>	26 Jul 2020	Engine			1
WoF Expiry:	28 Jan 2021	Odometer:	143,899 Kms	Good No:	19814331	Oil level	~		
VIN:	6G1EX5EV8AL440045	Next Service:	150000	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty a guide only. Conside		for age and mileag	e Parts have not	been dismontled or	Noise	V		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/	'h from cold. The	Vendor recommends	Cooling System			<u>I</u>
a full mechar	nical inspection prior to	purchase and tl	his can be arranged f	for an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	L	-0	S	-01-		Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission	-		<u> </u>
D = dent	sc dl					Operation	~		
R = rust PT = paint def						Noise	~		
C = crack				$+ \mathbb{N}$		Clutch			~
P = pin dent						CV joints			~
* = decals	sc 916			The	ETTPS-	Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant scuffs S D D D S						Performance	~		
		Note: son	e defects & blemishe	es may not be disr	blayed in the diagram	Hand Brake	~		<u> </u>
	pection Comments		le délects à blemisme	es may not be disp	ayed in the diagram		•	ofture	
RR wheel flap in boot						Tyres (lowest observed tread depth of tyres)   Left front 6 mm			
									mm
						Right front Left rear		5	mm
								5	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Rear wheel	-	meenspeede	<u>on comments</u>			Suspension			
Rear wheel	unve					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Average					Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		<u> </u>
	Clavabay	nanal missing				Indicators	~		
Panels	Giovebox	panel missing				Dashboard warning lights	~		<u> </u>
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
	-		•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
								-	
Inspecte	d by: Ca Thach					Date: 14 Jan 202	20		

I have read and understood this condition guide.

Name: .....

Signature: .....