

## **Basic Vehicle Condition Guide**

Report ID: 19,814,464

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Suspension performance

Steering performance

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Shock absorbers Air Conditioning / Heater

Spare

Coolant condition Performance

Radiator / Hoses (visual)

23 Sep 2019 Created:

Pass

~

~

/

V

1

/

Tyres (lowest observed tread depth of tyres)

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

5

4

1

/

/

/

1

/


2

Yes

Make: Model: Suzuki APV **Body Style:** Van Year: 2013 Registration: GZM374 **Reg Expiry:** 11 Oct 2019 WoF Expiry: **Odometer:** 30 Aug 2020 102,401 Kms **Good No:** 19814464 VIN: MHYGDN71V0030469 Next Service: **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Decal glue on fenders and bonnet Front bumper and LH head lamp misaligned Antenna broken Both headlamps not working

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Underbody surface rust Dent on LH sill rear Rear wheel drive

<u>Interior Comments</u>				
	Seats	Poor		
Ī	Carpets	Poor		
	Panels	Poor		
Г		Poor		

## **General Comments**

Dashboard

Rubbing noise from steering

**Road Conditions During Test Drive:** Dry

	Central locking	~				
	Remote locking		~			
	Sat. Nav. (basic test only)		~			
Kms:	Reversing camera		~			
Date: 23 Sep 2019						
Name: Signature:						

	Remote locking	~	
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)	~	
Evidence of Cam Belt Replacement: No	Kms:	Reversing camera	<b>'</b>
Inspected by: Mathew Varghese		Date: 23 Sep 2019	
have read and understood this condition guide.	Name:	Signature:	 