

Report ID: 19,816,415


Version: 3

Created: 30 Sep 2019

Make:	Lexus	Model:	CT200H	Body Style:	Hatchback
Year:	2011	Registration:	MKT535	Reg Expiry:	10 May 2020
WoF Expiry:	02 Sep 2020	Odometer:	74,648 Kms	Good No:	19816415
VIN:	JTHKD5BH902041212	Next Service:	90,000	Service Histor	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comments					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

Wet

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Mathew Varghese Inspected by:

Create	u. 3	J JCP 2	.017
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5	.0	mm
Right front	6.0		mm
Left rear	3.0		mm
Right rear	3.0		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		ı	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	l	-
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Poversing camera	./		

I have read and understood this condition guide.

Name:

Signature:

24 Sep 2019

Reversing camera