



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

|            |             |
|------------|-------------|
| Report ID: | 19,817,098  |
| Version:   | 1           |
| Created:   | 25 Sep 2019 |

|                                    |       |             |                   |
|------------------------------------|-------|-------------|-------------------|
| Make:                              | Honda | Body Style: | Hatchback         |
| Model:                             | FIT   | VIN:        | 7AT08G2YX19274296 |
| Year:                              | 2009  | Odometer:   | 71,572 Kms        |
| Road Conditions During Test Drive: | Dry   |             |                   |

| Electrical |                          | Transmission and Drive |                                  | Cooling System |                           | Exterior |                             |
|------------|--------------------------|------------------------|----------------------------------|----------------|---------------------------|----------|-----------------------------|
| 1          | Battery                  | 30                     | Fuel Flap Release                | 55             | Coolant Condition         | 78       | Under Carriage              |
| 2          | Headlights               | 31                     | Reversing Camera                 | 56             | Performance               | 79       | Sun Roof Operation          |
| 3          | Tail Lights              | 32                     | USB Port                         | 57             | Radiator/Hoses (visual)   | 80       | Front Windscreen (no chips) |
| 4          | High Stop Light          | 33                     | Window Lock Switch               | 58             | Suspension Performance    | 81       | Back Windscreen (no chips)  |
| 5          | Front Right Indicators   | 34                     | Operation                        | 59             | Steering Performance      | 82       | Side Windows (no chips)     |
| 6          | Front Left Indicators    | 35                     | Noise                            | 60             | Shock Absorbers           | 83       | Front Wiper Blades          |
| 7          | Rear Right Indicators    | 36                     | Clutch                           | 61             | Left Front                | 84       | Rear Wiper Blade            |
| 8          | Rear Left Indicators     | 37                     | CV Joints                        | 62             | Right Front               | 85       | R/H Mirror                  |
| 9          | Reversing Lights         | 38                     | Wheel Bearing                    | 63             | Left Rear                 | 86       | L/H Mirror                  |
| 10         | Rear Reflectors          | 39                     | Wheel Balance                    | 64             | Right Rear                | 87       | L/F Guard                   |
| 11         | Hazard Lights            | 40                     | Gearbox (Manual)                 | 65             | Spare                     | 88       | R/F Guard                   |
| 12         | Courtesy Lights          | 41                     | Engine Timing                    | 66             | Tools                     | 89       | L/H Doors                   |
| 13         | Dashboard Lights         | 42                     | Evidence of Cam Belt Replacement | 67             | AC Operation              | 90       | R/H Doors                   |
| 14         | Dashboard Dimmer Switch  | 43                     | Replaced at (odometer reading)   | 68             | Heater Fan                | 91       | L/H Sill                    |
| 15         | Number Plate Light       | 44                     | Front Brakes                     | 69             | Seatbelts                 | 92       | R/H Sill                    |
| 16         | Dashboard Warning Lights | 45                     | Rear Brakes                      | 70             | Horn                      | 93       | Boot/Tail Gate              |
| 17         | Speedo                   | 46                     | Handbrake                        | 71             | Seat Heaters              | 94       | Front Bumper                |
| 18         | Odometer                 | 47                     | Central Locking                  | 72             | Sun Visors                | 95       | Rear Bumper                 |
| 19         | Rev Counter              | 48                     | Remote Locking                   | 73             | Sun Visors Lights/Mirrors | 96       | Roof                        |
| 20         | Fuel Gauge               | 49                     | Number of Keys                   | 74             | Seats                     | 97       | Bonnet                      |
| 21         | Wipers Front/Rear        | 50                     | Oil Level                        | 75             | Carpets                   | 98       | Fuel Cap                    |
| 22         | Window Opener FL         | 51                     | Smokes and Fumes                 | 76             | Panels                    | 99       | Mud Flaps                   |
| 23         | Window Opener FR         | 52                     | Performance                      | 77             | Dashboard                 | 100      | WOF                         |
| 24         | Window Opener RL         | 53                     | Noise                            |                |                           |          |                             |
| 25         | Window Opener RR         | 54                     | Starter Motor                    |                |                           |          |                             |
| 26         | Rear View Mirrors        |                        |                                  |                |                           |          |                             |
| 27         | Radio (Basic Test Only)  |                        |                                  |                |                           |          |                             |
| 28         | CD (Basic Test Only)     |                        |                                  |                |                           |          |                             |
| 29         | Boot Open Switch         |                        |                                  |                |                           |          |                             |

**Turners Certification Key:**  
 ✓ = Pass  
 ✗ = Fail  
 • = Not applicable for this vehicle

|               |                  |       |             |
|---------------|------------------|-------|-------------|
| Inspected by: | Kyle Mills-Brown | Date: | 25 Sep 2019 |
|---------------|------------------|-------|-------------|

**I have read and understood this condition guide:**

|       |  |            |  |
|-------|--|------------|--|
| Name: |  | Signature: |  |
|-------|--|------------|--|