

Report ID: 19,818,538 Version: 1 25 Sep 2019 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2002	Registration:	AQU996	Reg Expiry:	12 Nov 2019	Engine	I	1	1
WoF Expiry:	22 Nov 2019	Odometer:	223,000 Kms	Good No:	19818538	Oil level	~		
VIN:	WVWZZZ1JZ2P38173	Next Service:	237000	Service History	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S R W	-0	SDPT SDPT		SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch	•		~
P = pin dent						CV joints	~		
* = decals SRSC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SD W SD RPT SD PT W SD						Performance			
Note: come defecte & blamichec may not be dicalayed in the diagram						Hand Brake	~		
Body inspection Comments							-	ofture	
Right taillight cracked Top of windscreen starting to delaminate						Tyres (lowest observed tread depth of tyres)			
Front bumper trim right side loose						Left front			mm
						Right front		2	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
					Suspension				
Speakers bl Right headl	ight not working					Suspension performance	~		
Side Mirror control nob missing						Steering performance	~		
Dip stick handle broken Signs of coolant in engine oil						Shock absorbers	~		
Left front seat lumber support adjuster nob missing						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories			
Seats	Avelage					Head lights		~	
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
	_					Window winder FR	~		
General Comments					Window winder RL	~			
Remote doesn't lock lock driver door Front tyres inner edge wear						Window winder RR	~		
Engine oil/coolant leak						Rear view mirrors	~		
Left rear tyre outer edge wear						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking		~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 25 Sep 2019									
I have read and understood this condition guide. Name:									