

Basic Vehicle Condition Guide

Report ID: 19,819,467


Version: 3

01 Mar 2020 Created:

Make: Model: Audi A3 **Body Style:** Hatchback Year: 2014 Registration: HEN763 Reg Expiry: 02 Jan 2020 WoF Expiry: **Odometer: Good No:** 14 Oct 2020 74,142 Kms 19819467 VIN: WAUZZZ8V5EA07874 Next Service: 88,983 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips in the windscreen Rear wiper washer not working

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

| Interior Comments | | | | | |
|-------------------|---------|--|--|--|--|
| Seats | Average | | | | |
| Carpets | Good | | | | |
| Panels | Good | | | | |
| Dashboard | Good | | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

| Inspected by: Mathew Varghese Date: 01 | Mar 20 |
|--|--------|
|--|--------|

| | Create | d: 0 | l Mar 2 | 020 | | | | |
|---------|------------------------------|-----------------|----------|-----|--|--|--|--|
| 7 | | Pass | Fail | N/A | | | | |
| | Engine Engine | | <u> </u> | | | | | |
| | Oil level | ~ | | | | | | |
| | Smoke & fumes | ~ | | | | | | |
| _ | Performance | \(\triangle \) | | | | | | |
| | Noise | ~ | | | | | | |
| | Cooling System | | | | | | | |
| | Coolant condition | ~ | | | | | | |
|] | Performance | ~ | | | | | | |
| | Radiator / Hoses (visual) | ~ | | | | | | |
| | Transmission | | | | | | | |
| | Operation | ~ | | | | | | |
| | Noise | ~ | | | | | | |
|] | Clutch | | | ~ | | | | |
| | CV joints | ~ | | | | | | |
|] | Wheel bearings | ~ | | | | | | |
| | Brakes | | | | | | | |
| | Performance | ~ | | | | | | |
| | Hand Brake | ~ | | | | | | |
| | Tyres (lowest observed treac | l depth | of tyre | es) | | | | |
| | Left front | į | 5 | | | | | |
| | Right front | (| 5 | mm | | | | |
| | Left rear | 4 | 4 | | | | | |
| 7 | Right rear | 4 | | mm | | | | |
| _ | Spare | | Yes | | | | | |
| | Suspension | | | | | | | |
| | Suspension performance | ~ | | | | | | |
| | Steering performance | <i>v</i> | | | | | | |
| | Shock absorbers | ~ | | | | | | |
| | Air Conditioning / Heater | | ! | | | | | |
| _ | Operation | ~ | | | | | | |
| | Electrical / Accessories | | | | | | | |
| | Head lights | ~ | | | | | | |
| | Tail lights | ~ | | | | | | |
| | Indicators | V V | | | | | | |
| | Dashboard warning lights | ~ | | | | | | |
| | Wipers (front & rear) | ~ | | | | | | |
| | Window winder FL | ~ | | | | | | |
| _ ¬ | Window winder FR | ~ | | | | | | |
| | Window winder RL | ~ | | | | | | |
| | Window winder RR | ~ | | | | | | |
| | Rear view mirrors | ~ | | | | | | |
| | Radio (basic test only) | ~ | | | | | | |
| | CD (basic test only) | ~ | | | | | | |
| L | Number of keys | 2 | _ | | | | | |
| 7 | Central locking | ~ | | | | | | |
| _ | Remote locking | ~ | | | | | | |
| | Sat. Nav. (basic test only) | | | ~ | | | | |
| | Reversing camera | | | ~ | | | | |
| _ | Data: 01 Mar 201 | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: