

Report ID: 19,820,471 Version: 1 27 Sep 2019 Created:

Make:	Chevrolet	Model:	MW	Body Style:	Hatchback	] [	Pass	Fail	N/A
Year:	2009	Registration:	LLU961	Reg Expiry:	27 Dec 2019	Engine			<u> </u>
WoF Expiry:		Odometer:	106,352 Kms	Good No:	19820471	Oil level	~		
VIN:	7AT02R4WX18362384	Next Service:		Service Histor	V: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		c 1 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	s w	-0	LS			Radiator / Hoses (visual)	~		
S = scratch	STE	AU			X	Transmission	•		
D = dent	6/6			The		Operation	~		
R = rust PT = paint def				í In	JHIH	Noise	~		
C = crack						Clutch			~
P = pin dent	HIC					CV joints	~		
* = decals	616				ELIPE IS	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significan	t scuffs		S S			Performance	~		
		Note: som	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed tread	-	oftvre	 (ک <sup>ر</sup>
Key in poor condition						Left front 2.8 mm			
						Right front		.0 .4	 
						Left rear			mm
Conditions During Body Inspection, D.						Right rear	5.5 mm 5.4 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories	•		
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		+
Dashboa	ard Average					Window winder FL	~		<u> </u>
						Window winder FR	~		<u> </u>
<u>General</u> (	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)		~	<u> </u>
						CD (basic test only)		•	~
						Number of keys	1		-
Pood Car	ditions During Test					Central locking	· ·		
Road Con	ditions During Tes	t Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	-		~
•	of Cam Belt Replac	-	lot Applicable	Kms:		Reversing camera			~
			11						
Inspecte	d by: Stuart Melbourr	ne				Date: 27 Sep 20	19		

I have read and understood this condition guide.

Name: .....

Signature: .....