

Basic Vehicle Condition Guide

Report ID: 19,820,722

Version:

Engine

Oil level

Created: 10 Oct 2019

Pass


Fail

N/A

Make: Model: Skoda Octavia **Body Style:** Sedan Year: 2014 Registration: HRW84 Reg Expiry: 20 Jan 2020 WoF Expiry: **Odometer: Good No:** 05 Jun 2020 66,970 Kms 19820722 VIN: TMBBK9NE2E0221537 Next Service: 76970 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Jeff Luke

Evidence of Cam Belt Replacement: No

Kms:

Smoke & fumes	·		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>v</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	>		
Tyres (lowest observed tread	d deptl	n of ty	/res)
Left front	177	3.0	mm
Right front	3.0		mm
Left rear	2	2.0	mm
Right rear	2.0 m		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	>		
Window winder FL	> > >		
Window winder FR	~		
Window winder RL			
Window winder RR	\(\times \)		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	~		

I have read and understood this condition guide.

Name:

Signature:

03 Oct 2019

Date: