

Report ID: 19,822,154 Version: 3 12 Dec 2019 Created:

Make:	Foton	Model:	Tunland	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	Registration:	KBN668	Reg Expiry:		Engine			1
WoF Expiry:	26 Sep 2019	Odometer:	34,385 Kms	Good No:	19822154	Oil level	~		<u> </u>
VIN:	LVAV2KBB8FJ052996	Next Service:	49000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition		~	
	SC					Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SC DIA			210		Operation	~		
PT = paint defe	ect NP			$\left[\left(\right) \right]$	17111	Noise	~		
C = crack						Clutch	~		
P = pin dent	sc				24114	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
All tyres just comply						Tyres (lowest observed tread depth of tyres)			
						Left front	4.0 mm		
						Right front	4.	0	mm
						Left rear	4.	0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 m		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Requires cooling system flush Rust under body						Suspension performance	~		
Rust under	body					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashhaa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	_					Window winder FR	~		
General Comments Glove box latch broken						Window winder RL			~
Glove box l	atch broken					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
	dia Dia M								
Inspected	d by: Dion Mair					Date: 02 Oct 20	9		

I have read and understood this condition guide.

Name:

Signature: