

Report ID: 19,822,359 Version: 1 07 Oct 2019 Created:

Make:	Holden	Model:	Epica	Body Style:	Sedan		Pass	Fail	N/A
Year:	2009	Registration:	EUW677	Reg Expiry:	26 Nov 2019	Engine			
WoF Expiry:	04 Dec 2019	Odometer:	120,900 Kms	Good No:	19822359	Oil level	~		
VIN:	KL3LA69LJ9B147207	Next Service:	130000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	V		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC W W	-0	LSC	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC SC W						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HIC				게	CV joints	~		
* = decals	PSCW			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W SC W						Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front		.9	mm
						Left rear		.0	mm
Condition	as During Padulas	naction	Deri			Right rear		-	
Conditions During Body Inspection: Dry						Right rear 9.7 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	ody inspection complet	•				Suspension performance	~		
	, , , ,					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Banala	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General C	Comments					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	2 V		
Road Con	unions During Tes	t Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
-	of Cam Belt Replac	-	lot Applicable	Kms:		Reversing camera			~
			11						•
Inspected by: Bailey Michel Date: 07 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: