

Report ID: 19,823,059 Version: 1 30 Sep 2019 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV	1[		Pass	Fail	N/A	
Year:	2005	<b>Registration:</b>	CLT884	<b>Reg Expiry:</b>	25 Oct 2019		Engine				
WoF Expiry:	20 Jun 2020	Odometer:	179,220 Kms	Good No:	19823059		Oil level	~			
VIN:	6FPAAAJGAT4Y75519	Next Service:	-	Service Histor	<b>y:</b> No		Smoke & fumes	~			
						il	Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	H	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full machanisal inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
	SC		SD SP	S	DW	1	Performance	~			
Key:				500-			Radiator / Hoses (visual)	~			
S = scratch D = dent							Transmission				
R = rust	PT SC W			210	HILD W		Operation	~			
PT = paint def	ect NP				101h		Noise	~			
C = crack					PT SC		Clutch			~	
P = pin dent	S PT SC				74116		CV joints	~			
* = decals				10	ELD'S		Wheel bearings	~			
SC = stone chips W = significant scuffs							Brakes				
vv = signincan	D PT SC W		PT DW		DW		Performance	~			
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram		Hand Brake	~			
Body Inspection Comments Windscreen stone chips/Badges missing/Bonnet struts fail/Wipers worn/FR wheel cap missing/FL tyre outer							<b>Tyres</b> (lowest observed tread depth of tyres)				
will damage/Rear tyres cracks							Left front	4 mn			
							Right front		5	mm	
						╽	Left rear		5	mm	
Conditions During Body Inspection: Wet						1	Right rear	5.	.5	mm	
						╎╎	Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments							Suspension				
4WD/Brake pads low/Excessive engine oil leak/Minor transmission oil leak/Underbody surface rust/Dent near							Suspension performance	~			
rear left jac	king point						Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater	1		1	
							Operation	~			
Interior Comments							Electrical / Accessories				
Seats	Average						Head lights	~			
	Rear floor	mats missing, dr	iver side wear				Tail lights	~			
Carpets							Indicators	~			
Panels	Roof lining	g sagging, steerir	ng wheel worn				Dashboard warning lights	~			
	Average						Wipers (front & rear)	~			
Dashboa	rd						Window winder FL	~			
						╎	Window winder FR	~			
General C	<u>Comments</u>						Window winder RL	~			
							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						]	Number of keys	1			
Road Conditions During Test Drive: Dry						ן ן	Central locking	~			
	-		•			ļ	Remote locking	~			
Engine Ti	ming Mechanism:	Timing	Chain				Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:			Reversing camera			~	
Inspected by: Ca Thach							Date: 30 Sep 2019				

I have read and understood this condition guide.

Name: .....

. . . . . . .

Signature: .....