

Report ID: 19,823,950 Version: 1 09 Oct 2019 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	JRG435	Reg Expiry:	29 Feb 2020	Engine			L
WoF Expiry:	02 Oct 2020	Odometer:	114,846 Kms	Good No:	19823950	Oil level	~		
VIN:	7AT0C139X16100295	Next Service:	124000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		$-\alpha$		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	sc w			The	SW SW	Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack				+		Clutch	~		
P = pin dent					세비	CV joints	~		
* = decals	sc 916			-NL	ELTPS w	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	1012.301		indy not be disp	ayea in the diagram			oftyre	
					Tyres (lowest observed tread depth of tyres) Left front 2.0 mm				
						Right front			mm mm
						Left rear		.0	mm
			_				4.	-	-
Conditions During Body Inspection: Dry						Right rear Spare	5.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
						•			
						Suspension performance	~		
						Steering performance	 		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	/ Weiage					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism	Timing				Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera									~
Inspected by: Greg Morgan Date: 04 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: