

Report ID: 19,824,010 Version: 2 23 Oct 2019 Created:

Make:	BMW	Model:	3 Series	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	LNG323	Reg Expiry:	22 Jul 2020	Engine			L
WoF Expiry:		Odometer:	82,825 Kms	Good No:	19824010	Oil level	~		
VIN:	WBAVR72070KW3953	Next Service:	· · · ·	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent S c W						Transmission			
						Operation	<b>v</b>		
R = rust				10	THIA	Noise	~		
PT = paint defe C = crack						Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	- MIK			AL-	ENR	Wheel bearings	~		
SC = stone chips							Brakes		
W = significant scuffs						Performance			
		Noto: com	ne defects & blemishes		laved in the diagram		~		
Body Insp	pection Comments	Note. son	le délects & blemisnes	illay not be disp	hayed in the diagram	Hand Brake			
					Tyres (lowest observed tread depth of tyres)				
						Left front	8.		mm
						Right front	8.		mm
						Left rear	8.		mm
Conditions During Body Inspection: Dry						Right rear	8.		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	N/A		
onder carriage & onder bonnet inspection comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Eddie Marsters Date: 15 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....