

Basic Vehicle Condition Guide

Report ID: 19,824,624


Version:

Created: 22 Oct 2019

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2013 Registration: HED876 Reg Expiry: 15 Jan 2020 WoF Expiry: **Odometer: Good No:** 21 Oct 2020 143,505 Kms 19824624 VIN: KMHST81XSEU229366 Next Service: 149,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Surface windscreen stone chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4WD

| <u>Interior Comments</u> | | | |
|--------------------------|--------------------|--|--|
| Seats | Good | | |
| Carpets | Floor mats missing | | |
| Panels | Good | | |
| Dashboard | Holes | | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement:

Not Applicable Kms:

| <u> </u> | _ | I | T | | |
|--|--------------|------|----------|--|--|
| | Pass | Fail | N/A | | |
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | / | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | > > > | | | | |
| Performance | / | | | | |
| Radiator / Hoses (visual) | / | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front 7.0 mm | | | | | |
| Right front | 7.0 | | mm | | |
| Left rear | 8 | .0 | mm | | |
| Right rear | 8 | .0 | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ' | | | | |
| Dashboard warning lights | | | | | |
| Wipers (front & rear) | V | | | | |
| Window winder FL | ✓ | | | | |
| Window winder FR | · | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | · · | | | | |
| Number of keys | 2 | | | | |
| Central locking | · | | | | |
| Remote locking | <i>y</i> | | | | |
| Sat. Nav. (basic test only) | | | ./ | | |
| Reversing camera | 1 | | | | |
| eversing curriera | | | <u> </u> | | |

I have read and understood this condition guide.

Jason Law

Name:

Signature:

22 Oct 2019

Date: