

## **Basic Vehicle Condition Guide**

Report ID: 19,825,612

Version: 1

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition

Created: 16 Oct 2019

Fail

N/A


Pass

V

Make: Model: **Body Style:** SUV Ssangyong Tivoli Year: 2015 Registration: MGU779 Reg Expiry: 10 Apr 2020 WoF Expiry: **Odometer: Good No:** 17 Oct 2020 65,924 Kms 19825612 VIN: **Next Service: Service History:** KPT30B1VSFP007833 75000 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

.

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair

Coolant Condition	<i>\\</i>		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	•	•	•
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	6	.0	mm
Right front	6	.0	mm
Left rear	6	.0	mm
Right rear	6	.0	mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	\( \times \)		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

04 Oct 2019

Date:

Name: ...... Signature: .....

have read	200 1100	10rc+00d+	hic cono	litian a	:
nave read	and un	161210001	ms conc		111(10