

Basic Vehicle Condition Guide

Report ID: 19,825,677


Version: 2

Created: 17 Oct 2019

Make: Model: Holden Malibu **Body Style:** Sedan Year: 2015 Registration: JAD257 Reg Expiry: 20 Apr 2020 WoF Expiry: **Odometer:** 22 Oct 2020 53,403 Kms **Good No:** 19825677 VIN: KL3GA69U9EB065479 Next Service: 61000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Genera	Comments

.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 11 Oct 2019

Name:

	Pass	Fail	N/A
Engine			1
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	V		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front		.0	mm
Right front		2.0	
Left rear		2.0	
Right rear		2.0	
Spare	Yes		mm
Suspension		103	
Suspension performance	~		
Steering performance	~		
Shock absorbers	<i>'</i>		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights			
Tail lights	<i>V</i>		
Indicators	V		
Dashboard warning lights			
Wipers (front & rear)	\(\times \)		
Window winder FL			
Window winder FR	V		
Window winder RL	V		
	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	<i>'</i>		
CD (basic test only)	V		
Number of keys	2		1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	~		

Signature: