

Report ID: 19,826,860 Version: 1 03 Oct 2019 Created:

Make:	Ssangyong	Model:	Actyon Sport	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	JYH304	<b>Reg Expiry:</b>	29 Sep 2019	Engine			
WoF Expiry:	19 Jul 2020	Odometer:	26,917 Kms	Good No:	19826860	Oil level	~		
VIN:	KPADA1E6SFP237211	Next Service:	27,500	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
			W PW		S	Performance	~		
Key:		-0	W PW			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defe	ect NP	r I		$\left[ \left( \right) \right]$		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	HIP				74116	CV joints	~		
* = decals SC 919 W						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W W						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Damage to the left tail light,						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front		4	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak,						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Good					Tail lights	~		
Carpets	0000					Indicators	~		
Panels	Average					Dashboard warning lights	~		
<u></u>	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						-	I	1	L
Inspected by: Donovan Matara Date: 03 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....