

Basic Vehicle Condition Guide

Report ID: 19,826,927

Pass

Version: 3

Engine

Oil level

Smoke & fumes

Created: 15 Nov 2019


Fail

N/A

Make: Model: Hyundai Tucson **Body Style:** SUV Year: 2007 Registration: **DUL543** Reg Expiry: 21 Apr 2020 **Odometer:** WoF Expiry: **Good No:** 10 Jun 2020 205,490 Kms 19826927 VIN: KMHJN81BR7U602208 Next Service: **Just Serviced Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Remote locking not working

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

Genera	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Dion Mair

Evidence of Cam Belt Replacement: No

Kms:

~		
~		
~		
~		
~		
•	•	
~		
~		
		~
~		
~		
	•	
~		
~		
d depth	of tyre	es)
4	.0	mm
4.0 r		mm
2.0 mn		mm
2.0 mm		mm
Yes		
	162	
	res	
·	res	
<i>V</i>	res	
\(\times \)	res	
<i>V V</i>	res	
V V	res	
<i>V V</i>	res	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	res	
V V V V V V	res	
\(\times \) \(\t	res	
V V V V V V V	res	
V V V V	Tes	
V V V V V	res	
V V V V V V	Tes	
V V V V V V V	Tes	
V V V V V V V	Tes	
V V V V V V V V	Tes	
V V V V V V V V V V V V V V V V V V V	Tes	
V V V V V V V V V V V V V V V V V V V	Tes	
V V V V V V V V V V V V V V V V V V V	Tes	
V V V V V V V V V V V V V V V V V V V	Tes	
V V V V V V V V		
	d depth	4.0 4.0 2.0 2.0

I have read and understood this condition guide.

Name:		

11 Nov 2019

~

Reversing camera