

I have read and understood this condition guide.

Report ID: 19,828,857 Version: 1 07 Oct 2019 Created:

Signature:

Make:	Nissan	Model:	Sunny	Body Style:	Sedan		Pass	Fail	N/A
Year:	1997	Registration:	DNT998	Reg Expiry:	13 Oct 2019	Engine			
WoF Expiry:	23 Oct 2019	Odometer:	231,715 Kms	Good No:	19828857	Oil level	~		
VIN:	7A8DH140706465480	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	V		
Key: S D S D R S D R S = scratch D = dent R = rust PT = paint defect						Radiator / Hoses (visual)	~		
						Transmission			
						Operation	~		
						Noise	~		
C = crack					R SC	Clutch	~		
P = pin dent						CV joints	~		
"= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts S PT W S D R S D R W S D W						Performance	~		
Body Incr	oction Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Acriel wand taged tagether						Tyres (lowest observed tread	l depth	of tyre	es)
Aerial wand taped together Right side monsoons cracked						Left front		1	mm
Rear bumper alignment Chip windscreen outside CVA						Right front			mm
Left rear tyre outer edge wear						Left rear		2 mm	
Conditions During Body Inspection: Dry						Right rear	2		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Boot rust Interior fan only works on full Radio not working						Suspension performance	~		
						Steering performance	~		
Engine oil leak						Shock absorbers		~	
Rear shocks worn						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	driver seat	tworn				Head lights	~		
	marks					Tail lights	~		
Carpets	manos					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	centre cor	. centre console lid broken					~		
Dashboa	rd					Window winder FL	~		
	•					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
			-			Remote locking			~
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Kyle Mills-Brown Date: 07 Oct 2019									

Name: