

Report ID: 19,829,685 Version: 1 08 Oct 2019 Created:

Make:	Honda	Model:	Accord	Body Style:	Wagon		Pass	Fail	N/A
Year:	2001	<b>Registration:</b>	FMW558	<b>Reg Expiry:</b>	19 Jul 2020	Engine		L	
WoF Expiry:	08 Aug 2020	Odometer:	241,421 Kms	Good No:	19829685	Oil level		~	
VIN:	7AT08G13X10208045	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S P SC S SC	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SDPTCS			TIS	SDC	Operation	~		
R = rust PT = paint defe				$\prod$	JUIL	Noise	~		
C = crack				$+ \vee$	S SC	Clutch			~
P = pin dent					세비	CV joints	~		•
* = decals	SDRCSCPP			-NL	ELLEN	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs S D SC S D SC						Performance	~		
		Note: som	e defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	) )
Badges missing,tailgate light cracked ,LF door mirror casing needs paint ,								mm	
						Right front			
								3	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Oil leak ,	inage a onder bor	meemspeede	<u>Comments</u>			Suspension			
Oll leak,						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation		~	
Interior Comments Average						Electrical / Accessories			
Seats	Avelage					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			-			Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 100,000						Reversing camera			~
Inspected by: Donovan Matara Date: 08 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....