

Basic Vehicle Condition Guide

Report ID: 19,829,778


Version: 5

02 Nov 2019 Created:

Make: Model: Volkswagen Touareg **Body Style:** SUV Year: 2006 Registration: JCG315 Reg Expiry: 08 Mar 2020 **WoF Expiry: Odometer: Good No:** 11 Mar 2020 181,855 Kms 19829778 VIN: WVGZZZ7LZ6D06246: Next Service: 190927 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Date: 07 Oct 2019 Inspected by: Jeff Luke

Name:

| _ | | | 1 | | | | |
|---|--|---------------------------------------|------|----------|--|--|--|
| | | Pass | Fail | N/A | | | |
| | Engine | | | 1 | | | |
| | Oil level | ~ | | | | | |
| | Smoke & fumes | \(\times \) | | | | | |
| | Performance | ~ | | | | | |
| Ì | Noise | ~ | | | | | |
| | Cooling System | | | | | | |
| | Coolant condition | ~ | | | | | |
| | Performance | <i>V</i> | | | | | |
| | Radiator / Hoses (visual) | ~ | | | | | |
| | Transmission | | | | | | |
| | Operation | ~ | | | | | |
| | Noise | ~ | | | | | |
| | Clutch | | | ~ | | | |
| | CV joints | ~ | | | | | |
| | Wheel bearings | ~ | | | | | |
| | Brakes | | | | | | |
| | Performance | ~ | | | | | |
| | Hand Brake | ~ | | | | | |
| | Tyres (lowest observed tread depth of tyres) | | | | | | |
| | Left front | 4 | .0 | mm | | | |
| | Right front | 4.0 | | mm | | | |
| | Left rear | 4.0 | | mm | | | |
| | Right rear | 4.0 | | mm | | | |
| | Spare | | Yes | | | | |
| | Suspension | | | | | | |
| | Suspension performance | ~ | | | | | |
| | Steering performance | ~ | | | | | |
| | Shock absorbers | ~ | | | | | |
| | Air Conditioning / Heater | | 1 | 1 | | | |
| | Operation | ~ | | | | | |
| | Electrical / Accessories | | | | | | |
| | Head lights | ~ | | | | | |
| | Tail lights | | | | | | |
| | Indicators | V | | | | | |
| | Dashboard warning lights | | | | | | |
| | Wipers (front & rear) | ~ | | | | | |
| | Window winder FL | \(\times \) | | | | | |
| | Window winder FR | ~ | | | | | |
| | Window winder RL | V | | | | | |
| | Window winder RR | ~ | | | | | |
| | Rear view mirrors | ~ | | | | | |
| | Radio (basic test only) | ~ | | | | | |
| | CD (basic test only) | ~ | | | | | |
| | Number of keys | 1 | | | | | |
| | Central locking | · | | | | | |
| | Remote locking | , , , , , , , , , , , , , , , , , , , | | | | | |
| | Sat. Nav. (basic test only) | _ | | / | | | |
| | Reversing camera | | | <i>y</i> | | | |
| | eversing curriera | | | | | | |

Signature: