

Report ID: 19,832,222 Version: 1 14 Oct 2019 Created:

| Make: | Volvo | Model: | XC70 | Body Style: | Wagon | | Pass | Fail | N/A |
|--|---|------------------|------------------------|--------------------|----------------------|-------------------------------|------|----------|----------|
| Year: | 2005 | | GPQ893 | Reg Expiry: | 05 Feb 2020 | Engine | | | L |
| WoF Expiry: | | Odometer: | 192,846 Kms | Good No: | 19832222 | Oil level | ~ | | |
| VIN: | YV1SZ595751205067 | Next Service: | | Service Histor | | Smoke & fumes | ~ | | |
| | | | • | | , | Performance | ~ | | |
| | port is not a warranty | | C 1 11 | D | | Noise | ~ | | |
| diagnostic te | a guide only. Conside sting undertaken. The | vehicle has beer | n driven up to 50km/ł | n from cold. The | Vendor recommends | Cooling System | • | | |
| a full mechar | ical inspection prior to | purchase and the | nis can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | D | -0 | | -161- | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | s 6/6 | | | The | EID S | Operation | ~ | | |
| R = rust PT = paint def | | | | 1 M | JHIH | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | | | | | 세비 | CV joints | ~ | | |
| * = decals | sc 916 | | | - NL | ELIPS- | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance | ~ | | |
| | | Note: som | ne defects & blemishes | s may not be disc | laved in the diagram | Hand Brake | ~ | | |
| | pection Comments | | | | | Tyres (lowest observed tread | - | oftvre | |
| Left front guard flare is coming unstuck off guard. Plastic cover on rear window wiper arm is missing. | | | | | | | | | mm |
| | | | | | | Right front | | .0 | mm |
| | | | | | | Left rear | | .0 .4 | mm |
| Canditia | | n a ati a n . | | | | Right rear | | | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear 4.0 mm Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | - | • | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | L |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | <u> </u> |
| Seats | Good | | | | | Head lights | ~ | | |
| | Cood | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | + |
| Panels | Good | | | | | Dashboard warning lights | ~ | | + |
| | | | | | | Wipers (front & rear) | ~ | | + |
| Dashboa | ord Good | | | | | Window winder FL | ~ | | |
| | 1 | | | | | Window winder FR | ~ | | <u> </u> |
| General Comments | | | | | | Window winder RL | ~ | | <u> </u> |
| Hand brake works fine, but handbrake travel needs adjustment. | | | | | | Window winder RR | ~ | | <u> </u> |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> |
| | | | | | | CD (basic test only) | ~ | | <u> </u> |
| | | | | | | Number of keys | 2 | L | I |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | <u> </u> |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: Y | 'es | Kms: 12 | 2,574 | Reversing camera | | | ~ |
| | | | | | | | 1 | 1 | 1 |
| Inspecte | d by: Jason Young | | | | | Date: 11 Oct 20 | 19 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: