

Report ID: 19,832,821 Version: 5 23 Oct 2019 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1999	<b>Registration:</b>	DPR909	<b>Reg Expiry:</b>	23 Feb 2020	Engine	1	I	
WoF Expiry:	26 Mar 2020	Odometer:	125,241 Kms	Good No:	19832821	Oil level	~		
VIN:	7A8C12H0706364989	Next Service:	127000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SC S D	-161-		Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent	w dl			TIN		Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack				+		Clutch	~		
P = pin dent	HID				게비	CV joints	~		
* = decals	sc 916			-No-	ETT P	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	· ·	oftyre	) (24
Stone chips And wiper mark front screen						Left front 5.0			mm
						Right front			mm
						Left rear	4		mm
			_						
Conditions During Body Inspection: Dry						Right rear 3.0 mm   Spare Yes			111111
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
<u></u>						-			
						Suspension performance Steering performance	~		
							~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	, we have					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanisms Comhelt						Remote locking			~
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Increate	Inspected by: Brian Hill Date: 09 Oct 2019								

I have read and understood this condition guide.

Name: .....

Signature: .....