

Report ID: 19,834,297 Version: 4 14 Nov 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:	GMD151	Reg Expiry:	20 Nov 2019	Engine	1	I	
WoF Expiry:	12 Sep 2020	Odometer:	205,933 Kms	Good No:	19834297	Oil level	~		
VIN:	MMU148FH0DH61685	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	DRWW				S	Performance	~		
Key:	DRW	-0		500-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S SC			715	SD SD	Operation	~		
PT = paint def	ect NP	IT I		$\left[\left(\right) \right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$	SC	Clutch			~
P = pin dent	HIS				74114	CV joints	~		
* = decals	sc 816			-Jul	ALD S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
<u>bouy ins</u>	pection Comments					Tyres (lowest observed treat	d depth	of tyre	es)
						Left front 5 r			
						Right front		5	mm
						Left rear		.5	mm
Conditions During Body Inspection: Wet						Right rear		.5	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Four wheel	drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
Intermittent vibration around 80 to 100 Kmph						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	1
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			V
							1	1	1
Inspecte	d by: Mathew Varghe	ese				Date: 14 Nov 20	19		

I have read and understood this condition guide.

Name:

Signature: