

Report ID: 19,835,040 Version: 5 16 Dec 2019 Created:

Make:	Mercedes-Benz	Model:	Sprinter	Body Style:	Van		Pass	Fail	N/A
Year:	2008	Registration:	ESP871	Reg Expiry:	06 Jun 2020	Engine		-	
	20 Jun 2020	Odometer:	233,227 Kms	Good No:	19835040	Oil level	~		
VIN:	WDB9066332S150565	Next Service:		Service Histor		Smoke & fumes	~		
			,.			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	S	-0	SD SDP		RP	Radiator / Hoses (visual)			~
S = scratch						Transmission			
D = dent						Operation	~		
R = rust				10		Noise			
PT = paint defects C = crack	ect 🛛			+		Clutch	~		
P = pin dent	Ho						~		
* = decals SC Q Q						CV joints			~
SC = stone chips						Wheel bearings			~
W = significant scuffs D S D D						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
LF window switch cover missing						Tyres (lowest observed tread depth of tyres)			
Windscreen stone chips						Left front	7 mm		-
						Right front	7		mm
						Left rear	7		mm
Conditions During Body Inspection:						Right rear	7 mm		
					Spare Yes				
Under Carriage & Under Bonnet Inspection Comments Unable to carry out hoist and underbody inspection due to vehicle oversized						Suspension			
Unable to c	arry out hoist and unde	rbody inspection	n due to vehicle oversi	zed		Suspension performance	~		
						Steering performance	~		
						Shock absorbers			~
						Air Conditioning / Heater			
L Interior Comments						Operation	✓		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
Carpote	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			٢
2wd Gear knob trim insecure						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
Evidence of Com Balt Deple comparts Net As all ask to Kings						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Ca Thach Date: 16 Dec 2019									

I have read and understood this condition guide.

Name:

Signature: