

Report ID: 19,835,462 Version: 4 05 Mar 2020 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:	GHU621	Reg Expiry:	16 Apr 2020	Engine	1		L
WoF Expiry:	04 Mar 2021	Odometer:	148,000 Kms	Good No:	19835462	Oil level	~		
VIN:	MNAUM2F50CW1081	Next Service:	157973	Service History	/: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SC P	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second se	Transmission	•		<u> </u>
D = dent	s sc			The		Operation	~		
R = rust PT = paint defe				\int	THA	Noise	~		
C = crack						Clutch	· ·		
P = pin dent						CV joints	•		~
* = decals	616			The	EITPS-	Wheel bearings	~		
SC = stone chips						Brakes	5		
W = significant scuffs S SC S SC S SC S SC						Performance	~		
		Note: som	e defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•		
Aftermarket parts fitted on the roof									
						Right front			mm
						Left rear	4		mm
						Right rear	5		mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Suspension	Yes		
Rear wheel	-	ince inspectie	<u>eonnento</u>			-			
near wheel	unve					Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			T
Seats						Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Screw hole	25				Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		<u> </u>
Conoral (Comments					Window winder FR	~		<u> </u>
						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		<u> </u>
Engina Ti	ning Machanism	Timeine - (Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jason Law Date: 05 Mar 2020									

I have read and understood this condition guide.

Name:

Signature: