

Report ID: 19,835,979 Version: 3 08 Nov 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013		HDM518	Reg Expiry:	10 Jan 2020	Engine			
WoF Expiry:	05 Nov 2020	Odometer:	132,020 Kms	Good No:	19835979	Oil level	~		
VIN:	WF0EXXGBBEDG6008		132,020 Kills	Service Histor		Smoke & fumes	~		
					. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Performance	v		
Key:	S	-0	LS			Radiator / Hoses (visual)	~ ~		
S = scratch						Transmission			
D = dent SC 66									<u> </u>
R = rust				10		Operation	~		
PT = paint defe	ect			$\square \cup$	SC SC	Noise	~		<u> </u>
C = crack P = pin dent	Ht			-		Clutch			~
*=decals SSC QQ						CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs W S S W						Brakes			
						Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Stone chips on front windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front	4.	0	mm
						Right front	4.	0	mm
						Left rear	4.	0	mm
Conditions During Body Inspection: Wet						Right rear	4.0 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
Shock a						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
						Central locking	~		
						Remote locking	~		1
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Mathew Varghese Date: 07 Nov 2019									

I have read and understood this condition guide.

Name:

Signature: