

Report ID: 19,836,085 Version: 1 16 Oct 2019 Created:

Make:	Nissan	Model:	Liberty	Body Style:	Wagon		Pass	Fail	N/A
Year:	2001	Registration:		Reg Expiry:	17 Oct 2019	Engine	I	1	I
WoF Expiry:	20 Jun 2020	Odometer:	156,888 Kms	Good No:	19836085	Oil level	~		
VIN:	7AT0DH6NX10016326	Next Service:	n/a	Service Histor	V: No	Smoke & fumes	~		
						Performance		~	
	port is not a warranty		6	Danta karra mat		Noise	~	-	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	P SC		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	scw 6/6			1n-	EL SC	Operation	~		
R = rust PT = paint defe				\int	THA	Noise	~		
C = crack					╫╫┼	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	sc 916			AL.	EITR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs S	$- \emptyset$	S SC			Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	1012.301		indy not be disp	ayea in the alagram		•	oftyre))
					Tyres (lowest observed tread depth of tyres) Left front 4.1 mm			mm	
						Right front			mm
						Left rear			-
						5.7 mm		-	
Conditions During Body Inspection: Dry						Right rear	5.6 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	/ surface rust	ince inspectie	connents			Suspension			
Right rear s	hock oil leak					Suspension performance	~		
Right front	inner c/v boot split					Steering performance	~		
						Shock absorbers		~	
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	0000					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
	-					Window winder FL	~		
Concrol						Window winder FR	~		
Engine lack	<u>Spower</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
Enging Th	ming Machanism	Timina	Chain			Remote locking			~
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~
Evidence	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Ian Dunn Date: 14 Oct 2019									

I have read and understood this condition guide.

Name: