

## **Basic Vehicle Condition Guide**

Report ID: 19,836,160

Pass

~

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 16 Oct 2019

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

8

8

1

/

/

/

1

1


2

Yes

Make: Model: Hyundai Terracan **Body Style:** SUV Year: 2004 Registration: **CEP389 Reg Expiry:** 04 Aug 2020 WoF Expiry: **Odometer:** 12 Jan 2020 190,730 Kms **Good No:** 19836160 VIN: KMHNM81CR4U14748 Next Service: 200000kms **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

| <u>Interior Comments</u> |         |  |  |  |
|--------------------------|---------|--|--|--|
| Seats                    | Average |  |  |  |
| Carpets                  | Average |  |  |  |
| Panels                   | Average |  |  |  |
| Dashboard                | Average |  |  |  |

## **General Comments**

Inspected by:

**Road Conditions During Test Drive:** Wet

**Engine Timing Mechanism:** Cambelt

Jeff Luke

**Evidence of Cam Belt Replacement:** 

|                   | Remote locking              | ~ |   |  |  |  |  |
|-------------------|-----------------------------|---|---|--|--|--|--|
|                   | Sat. Nav. (basic test only) |   | ~ |  |  |  |  |
| Kms:              | Reversing camera            |   | ~ |  |  |  |  |
| Date: 15 Oct 2019 |                             |   |   |  |  |  |  |
| Name: Signature:  |                             |   |   |  |  |  |  |

| l hava r | and and | understood | d thic c | ondition | auida |
|----------|---------|------------|----------|----------|-------|
|          |         |            |          |          |       |