



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,841,422
Version:	2
Created:	11 Nov 2019

Make:	Lexus	Body Style:	Sedan
Model:	IS250	VIN:	7AT0B00EX19038075
Year:	2007	Odometer:	87,042 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good						
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good						
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good				
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	61	Left Front	6	mm	87	L/F Guard	Good	88	R/F Guard	Good		
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	6	mm	89	L/H Doors	Good	90	R/H Doors	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓	63	Left Rear	6	mm	64	Right Rear	6	mm	91	L/H Sill	Good	92	R/H Sill	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	65	Spare	Yes	66	Tools	✓	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good
9	Reversing Lights	✓	39	Wheel Balance	✓	67	AC Operation	✓	68	Heater Fan	✓	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	69	Seatbelts	✓	70	Horn	✓	99	Mud Flaps	✓	100	WOF	✓			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	71	Seat Heaters	✓	72	Sun Visors	✓									
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good									
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		75	Carpets	Good	76	Panels	Average									
14	Dashboard Dimmer Switch	✓	44	Front Brakes	✓	Interior		77	Dashboard	Good										
15	Number Plate Light	✓	45	Rear Brakes	✓	67	AC Operation	✓	68	Heater Fan	✓									
16	Dashboard Warning Lights	✓	46	Handbrake	✓	69	Seatbelts	✓	70	Horn	✓									
17	Speedo	✓	Keys and Locking		47	Central Locking	✓	71	Seat Heaters	✓	72	Sun Visors	✓							
18	Odometer	✓	48	Remote Locking	✓	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	✓									
19	Rev Counter	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓							
20	Fuel Gauge	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓						
21	Wipers Front/Rear	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓						
22	Window Opener FL	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓									
23	Window Opener FR	✓	53	Noise	✓															
24	Window Opener RL	✓	54	Starter Motor	✓															
25	Window Opener RR	✓																		
26	Rear View Mirrors	✓																		
27	Radio (Basic Test Only)	✓																		
28	CD (Basic Test Only)	✓																		
29	Boot Open Switch	✓																		

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kane Quinn	Date:	11 Nov 2019
I have read and understood this condition guide:			
Name:		Signature:	