

		Shock absorbers	~	
		Air Conditioning / Heater		
		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	Good	Head lights	~	
Carpets	Good	Tail lights	~	
		Indicators	~	
Panels	Average	Dashboard warning lights	~	
Dashboard	Good	Wipers (front & rear)	~	
		Window winder FL	~	
		Window winder FR	~	
<u>General Comments</u> Engine misfiring - minor Engine oil leak - minor Bouncy suspension - RL shock leaking		Window winder RL	~	
		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
	CD (basic test only)	~		
	Number of keys	1		
Road Conditions During Test Drive: Dry		Central locking	~	
	Remote locking	~		
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: Not Applicable Kms:		Reversing camera		~
Inspected by:	Date: 19 Jun 2020			

I have read and understood this condition guide.

Name:

3

Pass

V

V

V

V

V

V

V

V

V

V

~

V

6

6

4

4.5

N/A

~

~

19 Jun 2020

Fail

N/A

V

~

mm

mm

mm

mm