

Report ID: 19,842,876 Version: 1 18 Oct 2019 Created:

Make:	Toyota	Model:	Corona	Body Style:	Sedan		Pass	Fail	N/A
Year:	1992	Registration:	WR1832	Reg Expiry:	03 Sep 2019	Engine			
WoF Expiry:	16 Mar 2020	Odometer:	195,967 Kms	Good No:	19842876	Oil level	~		
VIN:	7A8H6050797002296	Next Service:	200000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		SC P SC		D	Performance	~		
Key:	Bell	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	S D SC			210	HIVS	Operation	~		
PT = paint defe		F		$\left[\left(\right) \right]$		Noise	~		
C = crack					РТ	Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	sc 916			-NG		Wheel bearings	~		
SC = stone chips						Brakes			1
W = significan			P P		SC	Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			2S)
Front Grill Missing, Surface Rust in Engine Bay, Bonnet not Fitting Flush .								mm	
						Right front	6.	-	mm
						Left rear	4		mm
Conditions During Body Inspection: Dry						Right rear		6.0 mr	
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak low	er engine area, Surface	Rust on underbo	ody of Vehicle.			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	1					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		
Road Con	unions During Test	Unve:	Dry			Remote locking			~
Engine Tir	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 73,000						Reversing camera			~
	-1			, .					
Inspected by: Chris Buckley Date: 18 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: