

Report ID: 19,842,946 Version: 7 22 Oct 2019 Created:

Make:	Holden	Model:	Commodore	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	Registration:	GCK739	Reg Expiry:	07 Dec 2019	Engine			
WoF Expiry:	09 Oct 2020	Odometer:	99,655 Kms	Good No:	19842946	Oil level	~		
VIN:	6G1EX8E29CL614716	Next Service:	112,000km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key: S = scratch D = dent						Radiator / Hoses (visual)	~		
						Transmission			
D = dent R = rust	SD D			715	HIV	Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74116	CV joints	r		
* = decals	- Alt			-Jul		Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs S						Performance	V		
Podulaci	action Commonts	Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres		
Front bumper and lower grille loose						Left front 6.0			mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories		-	
Seats	Seats Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)		~	
Dashboa	rd Good					Window winder FL	~	-	
						Window winder FR	~		
General Comments						Window winder RL	~		
Rear wiper and spray n/w, A/C fan direction n/w, reverse camera n/w, boot cannot open from remote						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		I
Road Conditions During Test Drive: Dry						Central locking		~	
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera		~	
L	-							÷	
Inspected by: Eddie Marsters Date: 22 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: