

Basic Vehicle Condition Guide

Report ID: 19,844,765


Version: 1

Created: 06 Nov 2019

Make: Model: Ford Mondeo **Body Style:** Wagon Year: 2014 Registration: HUD280 Reg Expiry: 27 Nov 2019 WoF Expiry: **Odometer:** 01 Nov 2020 143,229 Kms **Good No:** 19844765 VIN: WF0GXXGBBGEJ5998: Next Service: 153250 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Grille in front bumper needs alignment,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------------------------------|--|--|
| Seats | wear and tear,minor stains , | | |
| Carpets | wear and tear,minor stains , | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

06 Nov 2019 Inspected by: Donovan Matara Date:

Name:

| | Pass | Fail | N/A | |
|------------------------------|---------------------------------------|---------|-----|--|
| Engine | • | • | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | V | | | |
| Noise | ~ | | | |
| Cooling System | • | | | |
| Coolant condition | ~ | | | |
| Performance | <i>v</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | • | | • | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | • | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | : | 3 | mm | |
| Right front | : | 3 | mm | |
| Left rear | 3 | | mm | |
| Right rear | 3 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | | | | |
| Window winder RL | ~ | | | |
| Window winder RR | \(\times \) | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | L | |
| Number of keys | 1 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |

Signature: