

I have read and understood this condition guide.

Report ID: 19,845,091 Version: 2 25 Oct 2019 Created:

Signature: .....

Make:	BMW	Model:	3251	Body Style:	Sedan		Pass	Fail	N/A	
Year:	1997	Registration:	CBM454	Reg Expiry:	01 Mar 2020	Engine				
WoF Expiry:	12 Feb 2020	Odometer:	142,971 Kms	Good No:	19845091	Oil level	~			
VIN:	WBACB82040AS56152	Next Service:	unknown	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:	s sc w	-0	SC W P SC		S SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation 🖌				
R = rust PT = paint defe				$\prod$	JHIH	Noise	~			
C = crack				$+ \mathbf{\nabla}$	R SC	Clutch			~	
P = pin dent						CV joints			~	
* = decals	SPSC 916			The	ET SPT	Wheel bearings	~		•	
SC = stone chips						Brakes				
W = significant scuffs SC S S P SC W S						Performance	~			
		Note: son				Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftura	) )	
					Tyres (lowest observed tread depth of tyres)			-		
						Left front		.0	mm	
						Right front		5.0 m		
						Left rear		4.0 mr		
Conditions During Body Inspection: Dry						5			mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
Oil leaks under engine.						Suspension				
Oil leaks un	der engine.					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation		~		
Interior Comments Drivers seat ripped						Electrical / Accessories				
Seats	Divers sea	at ripped				Head lights	~			
Carpets	Worn on d	rivers side.				Tail lights	~			
						Indicators	~			
Panels	Drivers do	or tabric coming	away around handle.			Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~			
						Window winder FL	~			
	-					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Slight engine misfire when cold. may need 98 fuel been sitting for a while Heater not warming up.						Window winder RR	~			
	5 1					Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
			•			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
L										
Inspected by: Daryll Timms Date: 23 Oct 2019										

Name: .....