

a full mechanical inspection prior to purchase and this can be arranged for an additional charge.			Cooling System					
u				Coolant condition	~			
v		S SC SSC	1L	Performance	~			
S = scratch D = dent				Radiator / Hoses (visual)				
				Transmission				
R = rust			1	Operation	~			
РТ	= paint defect			Noise	~			
	= crack		1	Clutch			~	
	= pin dent			CV joints	~			
* = decals SC = stone chips W = significant scuffs				Wheel bearings	el bearings 🖌			
				Brakes				
vv	S SC	S S S S S S S S S S S S S S S S S S S		Performance	~			
	Body Inspection Co	Note: some defects & blemishes may not be displayed in the diagram		Hand Brake	~			
Bonnet painted black,LF door mirror casing cracked ,				Tyres (lowest observed tread depth of tyres)				
				Left front 5 mi				
				Right front	ļ	5	mm	
				Left rear	5		mm	
Conditions During Body Inspection: Wet			רוך	Right rear	ļ	5	mm	
			41	Spare				
	Under Carriage & Under Bonnet Inspection Comments			uspension				
				Suspension performance	~			
				Steering performance	~			
				Shock absorbers	~			
				Air Conditioning / Heater				
				Operation		~		
ſ	Interior Comments			ectrical / Accessories				
	Seats	wear and tear,minor stains ,		Head lights	~			
	Comoto	Average		Tail lights	~			
	Carpets			Indicators	~			
	Panels	Average		Dashboard warning lights	~			
		Average		Wipers (front & rear)	~			
	Dashboard	-		Window winder FL	~			
			╣┌╴	Window winder FR	~			
<u>General Comments</u> CD stuck in CD player but still works,				Window winder RL	~			
				Window winder RR	~			
				Rear view mirrors	~			
				Radio (basic test only)	~			
				CD (basic test only)	~			
				Number of keys	1			
	Road Conditions During Test Drive: Wet			Central locking	~			
		-	╣Ӷ	Remote locking	~			
Engine Timing Mechanism: Timing Chain				Sat. Nav. (basic test only)			~	
	Evidence of Cam Be	It Replacement: Not Applicable Kms:		Reversing camera			~	
	Increased by Derry	avan Matara		Data: 22 Oct 201	0			
	Inspected by: Done	ovan Matara		Date: 22 Oct 201	9			

I have read and understood this condition guide.

Name:

Signature:

Report ID: 19,845,711

Pass

V

V

V

V

1

22 Oct 2019

Fail

N/A

Version:

Created: