

Report ID: 19,846,930 Version: 1 05 Nov 2019 Created:

| Make: | BMW | Model: | 3 Series | Body Style: | SUV | | Pass | Fail | N/A | |
|--|--|-----------------|------------------------|---------------------------------------|-----------------------|--|------|------|-----|--|
| Year: | 2005 | Registration: | LGE633 | Reg Expiry: | 21 Oct 2019 | Engine | | | | |
| WoF Expiry: | 31 Oct 2020 | Odometer: | 187,956 Kms | Good No: | 19846930 | Oil level | ~ | | | |
| VIN: | WBAVS12050KV95786 | Next Service: | 195000 | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | | | | Performance | V | | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismontled or | Noise | r | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | or an additional o | harge. | Coolant condition | V | | | |
| | S SC S | | S SC S SC | | S SC | Performance | V | | | |
| Key: | SSC S | -0 | 330 330 | | SSC | Radiator / Hoses (visual) | V | | | |
| S = scratch | | | | | | Transmission | | | 1 | |
| D = dent R = rust | s sc | | | 715 | HILS | Operation | ~ | | | |
| PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | | |
| C = crack | | | | | SC | Clutch | | | ~ | |
| P = pin dent | ssc dR | | | | 74116 | CV joints | ~ | | | |
| * = decals | | | | To . | ELD'S | Wheel bearings | ~ | | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | | |
| | S D SC S | | S SC | | S | Performance | ~ | | | |
| Body Incr | pection Comments | Note: som | ne defects & blemishes | may not be disp | blayed in the diagram | Hand Brake | ~ | | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front 3 m | | | mm | |
| | | | | | | Right front | 4 | 1 | mm | |
| | | | | | | Left rear | | 7 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6 mm | | mm | |
| | | | | | | Spare N/A | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | Operation | ~ | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats | Good | | | | | Head lights | ~ | | | |
| | Good | | | | | Tail lights | ~ | | | |
| Carpets | | | | | | Indicators | ~ | | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | | |
| | Good | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | iiu | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | ~ | | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | | |
| | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 1 | | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | | |
| | | 11.1 | | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Unknown | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ | |
| Inspector | Inspected by: Donovan Matara Date: 05 Nov 2019 | | | | | | | | | |
| | , | - | | | | Date. 03 1107 20 | - | | | |

I have read and understood this condition guide.

Name:

Signature: