

Report ID: 19,847,974 Version: 1 04 Nov 2019 Created:

Make:	Holden	Model:	Astra	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:		Reg Expiry:	01 Aug 2020	Engine			I
WoF Expiry:	09 Apr 2020	Odometer:	143,458 Kms	Good No:	19847974	Oil level	~		
VIN:	W0L0TGF485G073379	Next Service:	149417	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
			S SC S SC		S SC	Performance	~		
Key:		-0	330 330	$- \square$	- SSC	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc w			710	SC W	Operation	~		
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dP				74116	CV joints	~		
* = decals		10		10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S W		W		PW	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front	7.	.5	mm	
						Right front	6.	.1	mm
						Left rear	6.	.6	mm
Conditions During Body Inspection: Dry						Right rear	7.9 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbo	ody inspection complet	ed				Suspension performance	~		
						Steering performance	<		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
- Engine Ti	ming Mechanism	Cambel				Remote locking	~		
						Sat. Nav. (basic test only)			~
	ог сапт вен керіас	ement: Y	es	Kms: 12	20,000	Reversing camera			~
Inspected by: Bailey Michel Date: 04 Nov 2019									

I have read and understood this condition guide.

Name:

Signature: